Improvements for LPMS and Waterborne Commerce Data

Inland Waterways Users Board

Meeting No. 82

24 February 2017

Dr. Mark Sudol

Director, Navigation and Civil Works

Decision Support Center,

Institute for Water Resources



US Army Corps of Engineers
BUILDING STRONG®



Continued Improvements to LPMS and WCSC Data output and visualizations

- Improvements to LPMS website
 - Reports and data availability
- Refinements to WISDM 3.0 Navigation Viewer
 - Integrating field input now
 - Schedule for going live on both internal and external sites
- Socrata and improved data availability
- Live demonstrations



Navigation and Civil Works Decision Support Center at IWR

Team members

▶ Nancy Blyler HQ EGIS

Joel Schlagel IWR Geospatial and data

▶ Tim Pangburn CRREL Geospatial

Forrest Vanderbilt
IWR Interagency Data

▶ Steven Riley IWR Navigation Data

► Ruth Betts IWR Navigation Data

Courtney Greenley IWR Data outreach, social media

Mark Pointon IWR Navigation Lead

▶ Tom Podany
IWR WCSC Director


▶ Dale Brown IWR WCSC Data Manager

ome Page Browse Developers Support


Steven Rile

U.S. Army Corps of Engineers Navigation and Civil Works Decision Support Center

Explore Corps Open Data on Socrata



Showing all Unavailabilities, Stoppages





	Reason ⊕ :≡	Stoppage Duration	· · · · · · · · · · · · · · · · · · ·
		~	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
1 ≔		3,574,471	
2	Repairing lock or lock hardware	1,650,321	Yz'
3 ≔		1,099,110	
4 ≔	D Lock Ok; unused for other reason	484,225	
5 ≔	Other	428,633	
6		323,024	
7 ;≣	♠ Tow accident or collision	293,528	
8 ≔	△ Lock staff occupied with other dut	i 184,704	
o :=	Oh Debrie	177.440	· · · · · · · · · · · · · · · · · · ·

Closed (unmanned shift) Repairing lock or lock hardware

Lock Ok; unused for other reason (i.e. CG river closing etc)

■ Debris ■ Accident or collision in lock ■ Fog ■ Lock hardwa

Operations (run-spill-divert water, flush seals-reserve etc)

pairing lock or lock hardware

ing lock or lock equipment

her structure (i.e railway, pontoon, swing etc.)

nt malfunction Inspection or testing lock

collision Lock staff occupied with other duties



Live Demonstrations

- Updates on LPMS data
- WISDM 3.0; Navigation Viewer beta version
- Socrata initial data viewer



Questions?

Mark Sudol 703-428-7570

